



This installation will automatically upgrade the database to version 95.

EMS - about version 9.3.5

This document describes all the news in the actual release.
 The paragraph numbers below corresponds to the CRQ number used by GEL.

3516: A100/48 new handling

When using the A110 without an existing replacement you can use the serial "0" for the new serial. It will then automatically be replaced with a temporary serial in the format "110TMP1", "110TMP2" etc. It is not possible to conclude a repair when these serials is used.

Repair action

Upgrade info

Not prioritised

Fault report info

Rep. wsh **SE 59999 00**
 Serial No **A064863124**
 Rev. state **R5C**
 Product No **ROJ 208 831/3**
 Symptom S101 Hours

Remarks Remarks tech **RETURN**

Return reason: 3RR
 SWAP, RCD, Upgrade To:R5F
 2014-03-26 10:37 / XENS

Warranty **Out of warranty** Times rep **0**
 Origin **NL**
 Own workshop level **2** Previous

OTHER FAULT+WRITTEN REMARK

Code	Fault action	OLD Ser.No.	Rev.st.	OLD Prod.No.	New rev.st.	Rep.Ex.	FCD/RCD Document No
<input checked="" type="checkbox"/> A110	Replaced Sub Unit / N	TEST1	R1	BKV 106 24		<input type="checkbox"/>	ABC123

Code	Repair code desc	NEW Ser.No.	Rev.st.	NEW Prod.No.	Major	Sign.
<input checked="" type="checkbox"/> 48	FCD / RCD / SA Action	0	R1	BKV 106 24	<input type="checkbox"/>	SYSDBA

Action No. 1

Description

The temporary serial.

Code	Repair code desc	NEW Ser.No.	Rev.st.	NEW Prod.No.	Major	Sign.
<input checked="" type="checkbox"/> 48	FCD / RCD / SA Action	110TMP3	R1	BKV 106 24	<input type="checkbox"/>	SYSDBA



If you want to, the unit can be automatically put on hold (shown by the green color).
If you are using Place you can also get a note of where the unit is right now.

Fault report No.	Rev.state	Incoming serial No.	Product No.	Unit place	Prev place unit
1002024606	R5C	A064643978	ROJ 208 831/3		
1002024607	R5C	A064624646	ROJ 208 831/3	GOE TEST	
1002024608	R5C	A064643976	ROJ 208 831/3		
1002024609	R5C	A064863124	ROJ 208 831/3	GOE TEST	
1002024610	R5C	A064718959	ROJ 208 831/3		
1002024611	R5C	A064955922	ROJ 208 831/3		

When the replacement unit is available you change the temporary serial and add the correct serial.

Code	Fault action	OLD Ser.No.	Rev.st.	OLD Prod.No.	New rev.st.	Rep.Ex.	FCO/RCD Document No
A110	Replaced Sub Unit /	TEST1	R1	BKV 106 24		<input type="checkbox"/>	ABC123

Code	Repair code desc	NEW Ser.No.	Rev.st.	NEW Prod.No.	Major	Sign.
48	FCO / RCD / SA Action	NEW-SERIAL	R1	BKV 106 24	<input type="checkbox"/>	SYSDBA

Action No. 1

Description

After saving you can conclude and send back to the customer.

Not prioritised **OTHER FAULT-WRITTEN REMARK** Own workshop level 2 Previous

Code	Fault action	OLD Ser.No.	Rev.st.	OLD Prod.No.
A110	Replaced Sub Unit /	TEST1	R1	BKV 106 24

Code	Repair code desc	NEW Ser.No.	Rev.st.	NEW Prod.No.	Major	Sign.
48	FCO / RCD / SA Action	NEW-SERIAL	R1	BKV 106 24	<input type="checkbox"/>	SYSDBA

Conclude repair

Conclude repair

To Customer (recommended)

Swap store (default store)

Place for rev state **R5C**

OK Cancel

3520: A130 sync R-state - **Correction done**

When concluding after a A130 repair, a change of a R-state in a subunit resulted in change of the **outgoing** R-state for the **main** unit. Now corrected - such a change is only propagated to the unit table.

Problem description:

The screenshot displays a 'Repair action' form with several sections:

- Upgrade info:** A box labeled 'Not prioritised'.
- Fault report info:** Contains fields for 'Rep. wsh CN 52782 02', 'Serial No X172300974', 'Rev. state R15B', 'Product No BOE 602 14/1', and 'Symptom S101'. It also shows 'Warranty Out of warranty', 'Origin CN', and 'Times rep 1'. A 'RETURN' button is visible.
- Alt+P to change table:** A table with columns: Code, Fault action, MODIFIED Ser.No., Rev.st., MODIFIED Prod.No., New rev.st., Rep.Ex., FCO/RCD Document No. The table contains four rows, with the third row (A130 Modified Product / Su X172303263 R1A ROA 219 7774/1 R1A/B) highlighted in yellow. A red arrow points from this row to the 'Incoming item' section, and a blue arrow points from this row to the 'Additional items' section.
- Fault report:** Shows '1012863706', 'Ordered 2015-06-08 09:20', 'Repair type RETURN', 'Own workshop', 'Repaired at own wsh', and 'Rem: Return reason: SWAP'. It also includes 'Status ABGHEFYXQZ', 'Target date 2015-06-22', and 'FAR'.
- Incoming item:** Shows 'Serial No. IN X172300974', 'Rev. state R15B', 'Unit Prod. DXU21 BOE 602 14/1', 'Manuf. week 06W28', 'Symptom S101', 'Warranty Out of warranty', and 'Accepted 2006-07-12'.
- Additional items:** Shows 'Serial No. OUT X172300974', 'Rev. state R1A/B', 'Product No. BOE 602 14/1', and 'WSH'.
- Remarks:** A text area containing 'Return reason: SWAP 2015/06/08 09:25 / YWH'.

After this correction the main unit keeps the proper R-state (R15B/B in this case). This problem was probably introduced with another change in November 2014.



3516: A100/48 new handling

When using the A110 without an existing replacement you can use the serial "0" for the new serial. It will then automatically be replaced with a temporary serial in the format "110TMP1", "110TMP2" etc. It is not possible to conclude a repair when these serials is used.

Repair action

Upgrade info

Not prioritised

Fault report info

Rep. wsh **SE 59999 00**
 Serial No **A064863124**
 Rev. state **R5C**
 Product No **ROJ 208 831/3**
 Symptom S101 Hours

Remarks Remarks tech **RETURN**

Return reason: 3RR
 SWAP, RCD, Upgrade To:R5F
 2014-03-26 10:37 / XENS

Warranty **Out of warranty** Times rep **0**
 Origin **NL**

Own workshop level **2** Previous

OTHER FAULT+WRITTEN REMARK

Code	Fault action	OLD Ser.No.	Rev.st.	OLD Prod.No.	New rev.st.	Rep.Ex.	FCD/RCD Document No
<input type="checkbox"/> A110	Replaced Sub Unit /	TEST1	R1	BKV 106 24		<input type="checkbox"/>	ABC123

Code	Repair code desc	NEW Ser.No.	Rev.st.	NEW Prod.No.	Major	Sign.
<input type="checkbox"/> 48	FCD / RCD / SA Action	0	R1	BKV 106 24	<input type="checkbox"/>	SYSDBA

Action No. 1

Description

The temporary serial.

Code	Repair code desc	NEW Ser.No.	Rev.st.	NEW Prod.No.	Major	Sign.
<input type="checkbox"/> 48	FCD / RCD / SA Action	110TMP3	R1	BKV 106 24	<input type="checkbox"/>	SYSDBA

If you want to, the unit can be automatically put on hold (shown by the green color).

If you are using Place you can also get a note of where the unit is right now.

Fault report No.	Rev.state	Incoming serial No.	Product No.	Unit place	Prev place unit
1002024606	R5C	A064643978	ROJ 208 831/3		
1002024607	R5C	A064624646	ROJ 208 831/3	GOE TEST	
1002024608	R5C	A064643976	ROJ 208 831/3		
1002024609	R5C	A064863124	ROJ 208 831/3	GOE TEST	
1002024610	R5C	A064718959	ROJ 208 831/3		
1002024611	R5D	A064955922	ROJ 208 831/3		

When the replacement unit is available you change the temporary serial and adds the correct serial.

Code	Fault action	OLD Ser.No.	Rev.st.	OLD Prod.No.	New rev.st.	Rep.Ex.	FCO/RCD Document No
A110	Replaced Sub Unit /	TEST1	R1	BKV 106 24		<input type="checkbox"/>	ABC123

Code	Repair code desc	NEW Ser.No.	Rev.st.	NEW Prod.No.	Major	Sign.
48	FCO / RCD / SA Action	NEW-SERIAL	R1	BKV 106 24	<input type="checkbox"/>	SYSDBA

Action No. 1

Description

After saving you can conclude and send back to the customer.

Not prioritised **OTHER FAULT+WRITTEN REMARK** Own workshop level 2 Previous

Code	Fault action	OLD Ser.No.	Rev.st.	OLD Prod.No.
A110	Replaced Sub Unit /	TEST1	R1	BKV 106 24

Code	Repair code desc	NEW Ser.No.	Rev.st.	NEW Prod.No.	Major	Sign.
48	FCO / RCD / SA Action	NEW-SERIAL	R1	BKV 106 24	<input type="checkbox"/>	SYSDBA

Conclude repair

Conclude repair

- To Customer (recommended)
- Swap store (default store)

Place for rev state **R5C**